# Shiloh Church Road Site

Unified Command Update 1/7/20

# Agenda

- Radiation-Contaminated Debris
  - Types of radiation debris discovered
  - Shipment
  - Storage
- Contaminated Soil (Property #1)
  - Contaminants of Concern
  - Shipments to date
  - Explanation of cadmium and lead as Hazardous Waste
  - Explanation of "Underlying Hazardous Constituents" requirements for Hazardous Waste Landfills
  - Explanation of disposal of hazardous wastes (RCRA) versus disposal of PCBs (TSCA)
  - Proposal for treatment and disposal of mixed wastes
- Drinking Water Contamination
  - Status of residential sampling
  - Status of new treatment systems
  - Drum excavation area finding
- Next Steps

Radiation-Contaminated Debris
Types of radiation debris discovered





#### COMMON RADIOLOGICAL ITEMS Shiloh Church Road Site • Nathalie, VA









Item Description: Button Sources Isotope: Radium-226

Page 3 of 8

#### COMMON RADIOLOGICAL ITEMS Shiloh Church Road Site • Nathalie, VA







Item Description: Switch, similar to button source on end of switch Isotope: Radium-226

Page 4 of 8

#### COMMON RADIOLOGICAL ITEMS Shiloh Church Road Site • Nathalie, VA





Item Description: Cesium Boxes, look similar to car batteries Isotope: Cesium-137

Page 5 of 8

#### COMMON RADIOLOGICAL ITEMS Shiloh Church Road Site • Nathalie, VA





Item Description: Aircraft Ice Detection Device Isotope: Strontium-90

Page 6 of 8

#### COMMON RADIOLOGICAL ITEMS Shiloh Church Road Site • Nathalie, VA





Item Description: Paper-like material Isotope: Radium-226



Item Description: Tubing, very small Isotope: Radium-226

Page 7 of 8

#### COMMON RADIOLOGICAL ITEMS Shiloh Church Road Site • Nathalie, VA







Item Description: Various Metal Items Isotope: Radium-226





Item Description: Dirt, often solid blocks Isotope: Radium-226

Page 8 of 8

## Radiation Debris – Shipment and Storage

- 11/19 1 drum + 3 boxes of soil (approx. 9 cubic yards) shipped to Curie Environmental in Idaho for disposal
- Remaining radiation debris on Site is very low level activity. No special storage requirements
- Awaiting final disposal once all excavation is completed

### Contaminated Soil – Property #1

- Contaminants of concern Lead, Cadmium, PCBs, Dioxin
- Waste Staging Areas
  - Area #1 PCBs <1000 mg/kg, Lead (D008) and Cadmium (D006)</li>
  - Area #2 PCBs < 50, Lead (D008) and Cadmium (D006)</li>
  - IP Piles PCBs > 1000, Lead (D008) and Cadmium (D006)
  - TSCA Pile PCBs >50, Lead and Cadmium below HW limits
  - Drum Soil waste
- Soil and Debris disposal to Date
  - Area #2 132 tons (approx.)
  - PCB Debris 360 tons (approx.)

#### Metals vs. PCBs

RCRA (Resource Conservation Recovery Act )	TSCA (Toxic Substances Control Act)
Requirements for Hazardous Waste	Requirements for PCBs
Requirements for Landfills which accept HW (Subtitle C Landfills)	Regulates landfills that contain PCB waste
Contains Land Disposal Restriction (LDR) requirements regarding "what" can go into a HW Landfill	Soil and debris need to be segregated prior to arrival at PCB disposal facility

#### Lead and Cadmium as Hazardous Waste

	Cleanup Goal	Inorganics	TCLP Analysis Indicates whether the metal can leach
Lead	400	500-3000 (estimated)	>5 mg/l
Cadmium			> 1 mg/l

Areas of contamination are sampled for HW (TCLP) prior to excavation

Contaminated soils which exceed the limits for TCLP are considered Hazardous Waste and must be disposed of at an approved Hazardous Waste facility

Soil sent to a HW facility must be tested for Underlying Hazardous Constituents

### Underlying Hazardous Constituents

- Underlying Hazardous Constituents (UHCs) ... UHCs are trace amounts of hazardous chemicals (listed in 40 CFR 268.48) found in some hazardous wastes that do not in and of themselves cause the waste to be hazardous, but must be treated before the waste is deposited in a landfill. These substances must be treated to the Universal Treatment Standards prior to disposal.
- The soil which contains HW lead and cadmium CANNOT be accepted at ANY HW Subtitle C Landfill because of the UHCs (primarily dioxin)

### Contaminated Soil – Property #1


- Contaminants of concern Lead, Cadmium, PCBs, Dioxin
- Waste Staging Areas
  - Area #1 PCBs <1000 mg/kg, Lead (D008) and Cadmium (D006)</li>
  - IP Piles PCBs > 1000, Lead (D008) and Cadmium (D006)
  - TOTAL ESTIMATE: 3800 cubic yards

HW Landfill	TSCA Landfill
Cannot accept ANY of the waste above because of UHC exceedances	Cannot accept wastes above IF waste is HW under RCRA


## PROPOSAL



PCBs HW Lead HW Cadmium Add Stabilizer



PCBs
Non
HW
Metals
(Pass
TCLP
Testing)



Disposal at TSCA Facility

### Residential water treatment systems

- 6 new installations (Kinetico)
- Quarterly sampling scheduled for 2 years
- One data gapped filled no elevated levels of TCE or PCE
- Two data gaps still open

#### Drum Soil Area Discussion



- Heaviest contamination in NW corner. Drums were located on E side
- Contaminants > 1 mg/kg
  - Ethylbenzenes
  - Xylenes
  - Cresol compounds
  - Trichloroethene

### **Next Steps**

- Begin treatment/disposal of HW/PCB contaminated soil
- Geoprobe survey to determine extent of soil contamination in drum pit area
- Removal actions at Property #2
- Delineate Property #3 for removal of battery casings